

For the sake of this discussion, residue is the material left behind on the machine and work pieces after the water evaporates from the working solution. For a metalworking fluid to perform one of its key functions, provide in-process corrosion prevention, it is critical that the fluid leave a corrosion-resistant (residue) coating. Therefore, the question is not “does the fluid leave a residue” but rather “is the residue objectionable?” So once again we are forced to make a value judgment based on the specifics of our manufacturing situation with the understanding that the type of residue that the fluid leaves will affect carryoff and therefore fluid usage, machine function, filtration, machine and part cleanliness, and grinding wheel loading among other processes.

A simple but effective method for checking possible residue effects is to pour 5 ml. of coolant concentrate into a petri dish and leave it exposed to the air at room conditions for a month or more. In general, the longer the exposure to air the better; the more pronounced will be the effects of any oxidation. Properly formulated fluids will resist oxidation virtually indefinitely. The test can be repeated using various types of tramp oil contamination and mineral contamination.

Here at Master Fluid Solutions, we classify the results of these residue tests several different ways – first by its type and then by its solubility. These classifications are, admittedly, at least semi-subjective but when used to help compare fluids, can be quite powerful. The form classifications that we use are:

- The solubility classifications are:

- © 2025-2026 Master Fluid Solutions | Master Fluid Solutions® is a registered trademark of Master Chemical Corporation d/b/a Master Fluid Solutions.
Page 1/2 | www.masterfluids.com/na/en-us/ | Technical Bulletin # 058 | Created: 2025-04-29 | Revised: 2025-04-30 | PDF Printed: 2026-09-04

Characteristics of Metalworking Fluids - Product Residue

resoluble in working solution with minimum “manual” interference.

3. **Solvent** – Using solvent to clean machines and/or keep them clean is very impractical, increases costs and reduces the probability that it will be done on a regular proactive basis.
4. **Not soluble in any of the above alone** – while some residues seem to only be resolvable with sufficient elbow grease, a fair number are partially soluble in water or working solution and another portion resolvable in solvent. On a practical level, these are the most disagreeable residues and the most difficult to deal with.

In answer to the question “What can I do about residue in my operation?” the answer is “quite a bit!”

1. Select a fluid that will produce a residue that is acceptable in your application after balancing all the other issues.
2. Run the fluid at the appropriate concentration. You will get twice as much residue if you run the fluid at twice the minimum concentration necessary to do the job efficiently. In other words coolant management will affect residue as it does all other fluid functions.
3. Use the best possible water to mix the fluid. “Hard water” is one of the major sources of cations that react with the fluid components to make water-insoluble residues.
4. Remove chips and swarf from the sump as these metals can also be a source for cations.
5. Periodically “wash down” the machine using working solution to put working solution back where the water has evaporated. This also reduces the need for makeup fluid. Doing this on a regular basis makes it easier to keep the machine clean, etc, etc.
6. If there are difficult residues present on the machine, lightly spraying or brushing a compatible surfactant on the machine surface, and allowing it to penetrate before wash down, may be very helpful. (We recommend 10% TRIM® Whamex™ Machine Cleaner).

The residues that the fluid leaves are critical to the long-term success of a fluid, and just what the issues will be are very much a function of fluid selection, the water it is mixed with, and how it is managed.

NOTES:

Master Fluid Solutions’ “Guide to a Clean Shop,” which can be downloaded from our website or obtained from an authorized distributor, offers more information about residues and how to remove them.